

1997 Human Factors Information System Report for Plant Docket 281

Combined IR/ER/LER Report
Docket: 50-281 SURRY 2

Total Number of Hits in Date Range: 67
From 01/01/1997 to 12/31/1997
2x National Average: 266

Details	Department	Work Type	Docket/Report
Communications IR			
Number of items: 4			
Percent of total: 5.97			
51-Misunderstood /	M-Mechanical	M-Maint / Repair	50-281/1997002
	M-Mechanical		
53-Communication LT	G-Engineering	G-Design	50-281/1997002
	G-Engineering		
53-Communication LT	B-Plant Management	A-Administrative	50-281/1997007
	B-Plant Management		
54-No communication	O-Operations	O-Control Room Ops	50-281/1997009
	O-Operations		
Communications ER			
Number of items: 0			
Percent of total: 0			
Communications LER			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm IR			
Number of items: 2			
Percent of total: 2.99			
61-Labels LTA	O-Operations	B-Bal of Plant Ops	50-281/1997002
73-Excessive Noise	E-Electrical	H-Health Physics	50-281/1997002
Human-System Interface and Environm ER			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm LER			
Number of items: 0			
Percent of total: 0			
Management and Supervision IR			
Number of items: 11			
Percent of total: 16.42			
32-Supervision / co	B-Plant Management	U-Unknown	50-281/1996013
40-Individual Corre	B-Plant Management	U-Unknown	50-281/1996013
43-Operating Experi	B-Plant Management	U-Unknown	50-281/1997001
40-Individual Corre	O-Operations	A-Administrative	50-281/1997002
40-Individual Corre	G-Engineering	G-Design	50-281/1997002
40-Individual Corre	G-Engineering	G-Design	50-281/1997002
44-Corrective Actio	G-Engineering	G-Design	50-281/1997002
47-Root Cause LTA	G-Engineering	Z-Other	50-281/1997006
36-Scheduling and p	G-Engineering	M-Maint / Repair	50-281/1997007
36-Scheduling and p	W-Work Control / Sc	M-Maint / Repair	50-281/1997007
40-Individual Corre	O-Operations	Z-Other	50-281/1997009
Management and Supervision ER			
Number of items: 0			
Percent of total: 0			
Management and Supervision LER			
Number of items: 0			
Percent of total: 0			
Organizational Issues IR			
Number of items: 1			
Percent of total: 1.49			
28-Frequent use of	B-Plant Management	M-Maint / Repair	50-281/1997004
Organizational Issues ER			
Number of items: 0			
Percent of total: 0			
Organizational Issues LER			
Number of items: 0			

Work Factors IR

Number of items: 22

Percent of Total: 32.84

81-Work Package Qua	M-Mechanical	U-Unknown	50-281/1996013
83-Work practice or	O-Operations	U-Unknown	50-281/1996013
84-Non-conserv. dec	B-Plant Management	U-Unknown	50-281/1997001
87-Non-conservative	B-Plant Management	U-Unknown	50-281/1997001
87-Non-conservative	B-Plant Management	U-Unknown	50-281/1997001
87-Non-conservative	H-Health Physics	H-Health Physics	50-281/1997002
87-Non-conservative	H-Health Physics	H-Health Physics	50-281/1997002
83-Work practice or	H-Health Physics	H-Health Physics	50-281/1997002
83-Work practice or	U-Unknown	H-Health Physics	50-281/1997002
94-Log-keeping or r	B-Plant Management	A-Administrative	50-281/1997004
87-Non-conservative	E-Electrical	M-Maint / Repair	50-281/1997004
87-Non-conservative	E-Electrical	M-Maint / Repair	50-281/1997004
83-Work practice or	G-Engineering	G-Design	50-281/1997006
81-Work Package Qua	G-Engineering	G-Design	50-281/1997007
83-Work practice or	I-Instrumentation &	T-Testing	50-281/1997009
93-Awareness or att	G-Engineering	P-Procedure Dev	50-281/1997009
81-Work Package Qua	G-Engineering	F-Modification	50-281/1997009
81-Work Package Qua	G-Engineering	F-Modification	50-281/1997009
81-Work Package Qua	G-Engineering	F-Modification	50-281/1997009
83-Work practice or	O-Operations	S-Surveillance	50-281/1997010
91-Verification / p	O-Operations	B-Bal of Plant Ops	50-281/1997010

Work Factors ER

Number of items: 0

Percent of total: 0

Work Factors LER

Number of items: 0

Percent of total: 0

Page: 3

Date:06/28/1999